### ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈਡ ਕੁਆਟਰ)-ਕਮ-ਨੋਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ),ਪੰਜਾਬ,ਲੋ:ਨਿ:ਵਿ:, ਭਵਨ ਤੋਂ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।

=×

1	ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਐਨ.ਐਚ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।	2	ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਨਾਰਥ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।
3	ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਸੈਂਟਰਲ), ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗਤ੍ਹ।	4	ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਸਾਊਥ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।
5	ਮੁੱਖ ਇੰਜੀਨੀਅਰ, ਕੁਆਲਟੀ ਕੰਟਰੋਲ ਪੰਜਾਬ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮੋਹਾਲੀ।	6	ਮੁੱਖ ਇੰਜੀਨੀਅਰ, ਪੀ.ਆਰ.ਬੀ.ਡੀ.ਬੀ. ਪੰਜਾਬ ਰੋਡਜ਼ ਐਂਡ ਬ੍ਰਿਜ ਡਿਵੈਲਪਮੈਂਟ ਬੋਰਡ, ਮੋਹਾਲੀ।
7	ਮੁੱਖ ਇੰਜੀਨੀਅਰ, (ਬਿਜਲੀ) ਪੰਜਾਬ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।		

ਮੀਸੋ ਨੰ: 3302 /ਮੈਕ.

ਜਿਤੀ: 28/12/2017

ভিনা:- Maintenance/ annual repair and special repair norms for civil works in Government Buildings.

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਪੰਜਾਬ ਸਰਕਾਰ ਦੇ ਵਿੱਤ ਵਿਭਾਗ ਦੇ ਮੀਮੇਂ ਨੰ:8/2/2017/5ਐਫਬੀ.1/3081-82 ਮਿਤੀ 16.08.2017 ਰਾਹੀਂ ਜਾਰੀ ਹਦਾਇਤਾਂ ਦੇ ਮੱਦੇਨਜਰ ਇਮਾਰਤਾਂ ਦੀ ਮੈਨਟੀਨੈਂਸ ਦੇ ਲਈ ਸਪੱਸ਼ਟ ਨਾਰਮਜ਼ ਦੀ ਅਣਹੋਂਦ ਕਾਰਨ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ.ਕ੍ਰ.)-ਕਮ-ਨੌਡਲ ਅਫ਼ਸਰ ਇਮਾਰਤਾਂ ਦੇ ਮੀਮੇਂ ਨੰ:237/5/ਨਿਰਮਾਣ ਮਿਤੀ 15.09,2017 ਰਾਹੀਂ ਇੰਜ: ਏ.ਐਸ. ਬਰਾਤ, ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ ਦੀ ਕਨਵੀਨਰਸ਼ਿੱਪ ਅਧੀਨ ਇੱਕ ਕਮੇਟੀ ਗਠਿਤ ਕੀਤੀ ਗਈ ਸੀ। ਕਮੇਟੀ ਵੱਲੋਂ ਦਿੱਤੀਆਂ ਗਈਆਂ ਸਿਫਾਰਸਾਂ ਨੂੰ ਮੁੱਖ ਇੰਜੀਨੀਅਰਾਂ ਦੀ ਮੀਟਿੰਗ ਵਿੱਚ ਰਿਵੀਊ ਕਰਨ ਉਪਰੰਤ ਪ੍ਰਵਾਨ ਕੀਤਾ ਗਿਆ ਹੈ। ਸਰਕਾਰੀ ਇਮਾਰਤਾਂ ਦੀ ਮੋਨਟੀਨੈੱਸ/ਸਲਾਨਾ ਮੁਰੰਮਤ ਅਤੇ ਸਪੈਸ਼ਲ ਰਿਪੇਅਰ ਦੇ ਨਾਰਮ ਨੱਥੀ ਅਨੈਕਚਰ-1, ਅਨੈਕਚਰ-2, ਅਨੈਕਚਰ-3, ਅਨੈਕਚਰ-4 ਅਤੇ ਅਨੈਕਚਰ-5 ਵਿੱਚ ਦਰਸਾਏ ਗਏ ਹਨ, ਇੰਨ੍ਹਾਂ ਨਾਰਮਜ਼ ਦੇ ਅਧਾਰ ਤੇ ਵੱਖ-ਵੱਖ ਤਰ੍ਹਾਂ ਦੀਆਂ ਇਮਾਰਤਾਂ ਦੀ ਮੈਨਟੀਨੈਂਸ ਦੇ ਸਾਲਾਨਾ ਪ੍ਰੋਗਰਾਮ/ਬਜਟ ਪ੍ਰੋਵੀਜ਼ਨ ਅਤੇ ਡਿਟੇਲਡ ਅਨੁਮਾਨ ਤਿਆਰ ਕੀਤੇ ਜਾਣ।

ਨੱਥੀ/ਉਪਰੋਕਤ ਅਨੁਸਾਰ

ਸੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ.ਕ.)

ਕਮ– ਨੌਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ,

ਨ੍ਹਿਲੋ:ਨਿ:ਵਿ: ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ: 3303 / ਅ Hast: 28/12/2017

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਹੇਠ ਲਿਖਿਆਂ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਲਈ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ:-

।. ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਹਲਕਾ, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

2. ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।

3. ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।

਼ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਨੰ:1, ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖ਼ਾ, ਪ੍ਰਟਿਆਲਾ।

ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ.ਕ.)

ਕਮ- ਨੈਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ, ਨ੍ਹਾਲੋ:ਨਿ:ਵਿ: ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ। 「Wo mae s: 3304/ Ha. 「Hoof: 28 12 2017

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਸਾਰੇ ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰਜ, ਉਸਾਰੀ ਹਲਕਾ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਅੰਮ੍ਰਿਤਸਰ, ਬਠਿੰਡਾ, ਚੰਡੀਗੜ੍ਹ, ਫਿਰੋਜਪੁਰ, ਫਰੀਦਕੋਟ, ਹੁਸ਼ਿਆਰਪੁਰ, ਜਲੰਧਰ–1, ਜਲੰਧਰ–2, ਲੁਧਿਆਣਾ, ਪਟਿਆਲਾ–1, ਪਟਿਆਲਾ–2, ਪਠਾਨਕੋਟ, ਸੰਗਰੂਰ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਲਈ ਭੇਜਿਆ ਜਾਂਦਾ

> ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ (ਨਿਰਮਾਣ) ਵਾ: ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ:ਕੁ:)-ਕਮ-ਨੋਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।

โบ้อ พ์ละ ธ์: 3305 /bta. fust: 28/12/2017

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਹੇਠ ਲਿਖਿਆਂ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਲਈ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ:-

- ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ (ਡੀ.ਆਰ.ਡੀ.) ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ (ਪੀ. ਐਂਡ ਆਈ.), ਮੁੱਖ ਦਫਤਰ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੋਂ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ/ਪਟਿਆਲਾ।
- ਸਾਰੇ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਮੁੱਖ ਦਫਤਰ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।

3. ਸਾਰੇ ਭਾਗ ਮੁਖੀ, ਮੁੱਖ ਦਫਤਰ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।

ਨੱਥੀ/ਉਪਰੋਕਤ ਅਨੁਸਾਰ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ (ਨਿਰਮਾਣ) ਵਾ: ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ:ਕੁ:)-ਕਮ-ਨੋਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ। ਵਿਸ਼ਾ:-ਮਿਨਟਸ ਆਫ ਮੀਟਿੰਗ ਮਿਤੀ 15-12-2017 ਬਾਅਦ ਦੁਪਹਿਰ 3:00 ਵਜੇ ਇੰਜ: ਏ.ਕੇ.ਸਿੰਗਲਾ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ:ਕੁ:/ਐਨ.ਐਚ.)-ਕਮ-ਨੌਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ ਜੀ ਦੀ ਪ੍ਰਧਾਨਗੀ ਹੇਠ ਬਾਬਤ ਮੇਨਟੀਨੈੱਸ/ਸਲਾਨਾ ਮੁਰੰਮਤ ਅਤੇ ਸਪੈਸ਼ਲ ਰਿਪੇਅਰ ਦੇ ਨਾਰਮ ਫਿਕਸ ਕਰਨ ਸਬੰਧੀ।

ਇਸ ਮੀਟਿੰਗ ਵਿੱਚ ਹੇਠ ਲਿਖੇ ਅਧਿਕਾਰੀ ਸ਼ਾਮਿਲ ਹੋਏ।

	ਇੰਜ: ਜੇ.ਐਸ. ਮਾਨ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਸੈਂਟਰਲ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।	2	ਇੰਜ: ਏ.ਕੇ. ਸਿੰਗਲਾ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ:ਕੁ:/ਐਨ.ਐਚ)-ਕਮ-ਨੌਂਡਲ ਅਫਸਰ (ਇਮਰਤਾਂ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।
3	ਇੰਜ: ਅਰਵਿੰਦਰ ਸਿੰਘ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਨਾਰਥ), ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।	4	ਇੰਜ: ਐਸ.ਕੇ. ਗੁਪਤਾ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਸਾਊਥ) ਪੰਜਾਬ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ।
5	ਇੰਜ: ਪੀ.ਜੇ. ਅਰੋਡਾ ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਹਲਕਾ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸਾਖਾ, ਚੰਡੀਗਤ੍ਹ।	6	ਇੰਜ: ਏ.ਪੀ.ਐਸ. ਬਰਾੜ ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਹਲਕਾ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।
7	ਇੰਜ: ਹਰੀਸ਼ ਗੋਇਲ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਕਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸੰਗਰੂਰ।	8	ਇੰਜ: ਪੀ.ਜੇ. ਅਰੋੜਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।
7	ਰਿੰਜ: ਨਵੀਨ ਮਿੱਤਲ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਨੰ:1, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖ਼ਾ, ਪਰਿਆਲਾ।	10	ਇੰਜ: ਭੁਪਿੰਦਰ ਸਿੰਘ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ (ਨਿਰਮਾਣ), ਮੁੱਖ ਦਫਤਰ, ਨੌਡਲ ਅਫਸਰ (ਇਮਰਤਾਂ) ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਚੰਡੀਗੜ੍ਹ।

ਸਭ ਤੋਂ ਪਹਿਲਾਂ ਮੁੱਖ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਸਾਰੇ ਭਾਗ ਲੈਣ ਵਾਲੇ ਅਧਿਕਾਰੀਆਂ ਨੂੰ ਜੀ ਆਇਆਂ ਆਖਿਆ। ਇਜ:ਏ.ਕੇ. ਸਿੰਗਲਾ ਮੁੱਖ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਦੱਸਿਆ ਗਿਆ ਕਿ ਪੰਜਾਬ ਸਰਕਾਰ ਦੇ ਵਿੱਤ ਵਿਭਾਗ ਦੇ ਮੀਮੋ ਨੰ:ਲ/2/2017-5ਐਫਬੀ.1/3081-82 ਮਿਤੀ 16.08.2017 ਰਾਹੀਂ ਜਾਰੀ ਹਦਾਇਤਾਂ ਦੇ ਮੱਦੇਨਜਰ ਇਮਾਰਤਾਂ ਦੀ ਮੈਨਟੀਨੈਂਸ ਦੇ ਲਈ ਸਪੱਸ਼ਟ ਨਾਰਮਜ਼ ਦੀ ਅਣਹੋਂਦ ਕਾਰਨ ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ.ਕੁ.)-ਕਮ-ਨੌਡਲ ਅਫ਼ਸਰ (ਇਮਾਰਤਾਂ) ਦੇ ਮੀਮੋ ਨੰ: 2375/ਨਿਰਮਾਣ ਮਿਤੀ 15.09.2017 ਰਾਹੀਂ ਇੰਜ: ਏ.ਐਸ. ਬਰਾੜ, ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ ਦੀ ਕਨਵੀਨਰਸ਼ਿੱਪ ਅਧੀਨ ਇੱਕ ਕਮੇਟੀ ਗਠਿਤ ਕੀਤੀ ਗਈ ਸੀ। ਕਮੇਟੀ ਵੱਲੋਂ ਆਪਣੀਆਂ ਸਿਫਾਰਸ਼ਾਂ ਉਨ੍ਹਾਂ ਦੇ ਮੀਮੋ ਨੰ: 6155 ਮਿਤੀ 03.11.2017 ਰਾਹੀਆਂ ਭੇਜੀਆਂ ਗਈਆਂ ਸਨ। ਕਮੇਟੀ ਵੱਲੋਂ ਦਿੱਤੀਆਂ ਗਈਆਂ ਸਿਫਾਰਸ਼ਾਂ ਜ਼ੋ ਮੈਬਰਾਂ ਨੂੰ ਭੇਜੀਆਂ ਜਾ ਚੁੱਕੀਆਂ ਸਨ, ਨੂੰ ਲਾਗੂ ਕਰਨ ਤੋਂ ਪਹਿਲਾਂ ਵਿਸਥਾਰਪੂਰਵਕ ਵਿਚਾਰ ਵਟਾਂਦਰੇ ਦੀ ਜਰੂਰਤ ਹੈ। ਵੱਖ-ਵੱਖ ਹਾਜ਼ਰ ਹੋਏ ਮੈਂਬਰਾਂ ਵੱਲੋਂ ਹੇਠ ਦਿੱਤੇ ਗਏ ਵਿਚਾਰ ਦਿੱਤੇ ਗਏ:-

ਇੰਜ: ਪੀ.ਜੇ. ਅਰੋੜਾ ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਹਲਕਾ, ਚੰਡੀਗੜ੍ਹ ਵੱਲੋਂ ਉਨ੍ਹਾਂ ਦੇ ਹਲਕੇ ਅਧੀਨ ਮੈਨਟੇਨ ਕੀਤੀਆਂ ਜਾ ਰਹੀਆਂ ਇਮਾਰਤਾਂ ਵਿੱਚ ਦੋ ਇਮਾਰਤਾਂ ਜਿਵੇਂ ਕਿ ਸਿਵਲ ਸਕੱਤਰ-2, ਬਲਾਕ-ਬੀ, ਸੈਕਟਰ-9 ਚੰਡੀਗੜ੍ਹ ਅਤੇ ਸੈਕਟਰ-39 ਸੀ ਵਿਖੇ 96 ਨੰਬਰ ਹਾਉਸਿਸ ਚੰਡੀਗੜ੍ਹ ਦੇ 2016-17 ਦੇ ਅਨੁਮਾਨ ਪੇਸ਼ ਕੀਤੇ ਗਏ। ਇੰਨ੍ਹਾਂ ਅਨੁਮਾਨਾਂ ਅੱਪਭੇਟ ਕੀਤਾ ਰੇਟਾਂ ਨਾਲ ਵਾਚਨ ਤੇ ਪਾਇਆ ਗਿਆ ਕਿ ਸਿਵਲ ਸਕੱਤਰ-2 ਦੇ ਇਮਾਰਤ ਦੀ ਓਵਰਆਲ ਲਗਭਗ ਲਾਗਤ 15 ਰੁਪਏ ਪ੍ਰਤੀ ਵ:ਫੁੱਟ ਬਣਦੀ ਹੈ। ਰਿਹਾਇਸ਼ੀ ਇਮਾਰਤ ਦੀ ਲਗਭਗ ਲਾਗਤ 50 ਪ੍ਰਤੀ ਵ:ਫੁੱਟ ਬਣਦੀ ਹੈ, ਇੰਨ੍ਹਾਂ ਅਨੁਮਾਨਾਂ ਵਿੱਚ 28 ਆਇਟਮਾਂ ਦੀ ਪ੍ਰੀਓਡੀਸਿਟੀ ਲੈਂਦੈ ਹੋਏ ਅਨੁਮਾਨ ਤਿਆਰ ਕੀਤਾ ਗਏ ਹਨ। ਰਿਹਾਇਸ਼ੀ ਇਮਾਰਤ ਦੀ ਲਾਗਤ ਪ੍ਰਤੀ ਵਰਗ ਫੁੱਟ ਬਹੁਤ ਜਿਆਦਾ ਜਾਪਦੀ ਹੈ। ਵਿਚਾਰ ਕੀਤਾ ਗਿਆ ਕਿ ਬੇਹਤਰ ਹੋਵੇਗਾ ਕਿ CPWD Maintenance-2012 ਦੇ ਆਧਾਰ ਤੇ ਬਜਟ ਨਿਰਧਾਰਤ ਕਰਨ ਲਈ ਨਾਰਮ ਫਿਕਸ ਕੀਤੇ ਜਾਣ।

2	ਇੰਜ: ਜੇ.ਐਸ.ਮਾਨ, ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਸੈਂਟਰਲ),ਪੰਜਾਬ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭ ਤੇ ਮ ਵੱਲੋਂ ਦੱਸਿਆ
	ਗਿਆ ਕਿ ਚੰਡੀਗੜ੍ਹ ਵਿਖੇ ਵੀ.ਆਈ.ਪੀ. ਰਿਹਾਇਸ਼ੀ ਇਮਾਰਤਾਂ ਜਿਵੇਂ ਕਿ ਮਾਨਯੋਗ ਮੁੱਖ ਮੰਤਰੀ ਜੀ ਪੰਜਾਬ
	ਦੀ, ਮੰਤਰੀ ਸਾਹਿਬਾਨਾਂ ਦੀ ਰਿਹਾਇਸ਼, ਐਮ.ਐਲ.ਏ. ਰਿਹਾਇਸ਼ਾਂ, ਆਈ.ਏ.ਐਸ. ਅਤੇ ਆਈ.ਪੀ.ਐਸ.
	ਅਧਿਕਾਰੀਆਂ ਦੀ ਰਿਹਾਇਸ਼ਾਂ ਆਦਿ ਨੂੰ ਪ੍ਰੀਓਡੀਕਲ ਰਿਪੇਅਰ ਤੋਂ ਬਿਨ੍ਹਾਂ ਵੀ ਆਇਟਮਾਂ ਹਰ ਸਾਲ ਕਰਨ
	ਲਈ ਕਿਹਾ ਜਾਂਦਾ ਹੈ, ਜਿਸ ਕਾਰਨ ਐਨੂਅਲ ਰਿਪੇਅਰ ਦੀ ਬਜਟ ਲਾਗਤ ਦੇ ਅੰਦਰ-ਅੰਦਰ ਕੰਮ ਨੇਪਰੇ ਨਹੀਂ
	ਚੜਦੇ। ਇਸ ਕਰਕੇ ਸਰਬਸੰਮਤੀ ਨਾਲ ਫੈਸਲਾ ਕੀਤਾ ਗਿਆ ਕਿ ਇੰਨ੍ਹਾਂ ਇਮਾਰਤਾਂ ਲਈ ਬਜਟ ਸਲਾਨਾ
	ਪ੍ਰੋਗਰਾਮ ਵਿੱਚ ਅਸਲ ਦੇ ਅਧਾਰ ਤੇ ਵਿਵਸਥਾ ਕਰਨ ਦੇ ਨਾਰਮ ਨਿਰਧਾਰਤ ਕੀਤਾ ਜਾਣ।

3 ਇੰਜ:ਐਸ.ਕੇ. ਗੁਪਤਾ, ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਦੱਖਣ) ਪੰਜਾਬ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭ ਤੇ ਮ ਵੱਲੋਂ ਇੰਜੀਨੀਅਰ ਏ.ਐਸ.ਬਰਾੜ, ਨਿਗਰਾਨ ਇੰਜੀਨੀਅਰ ਦੀ ਕਮੇਟੀ ਵੱਲੋਂ ਭੇਜੀਆਂ ਗਈਆਂ ਸਿਫ਼ਾਰਸਾਂ ਨੂੰ ਵਾਚਨ ਉਪਰੰਤ ਕੁੱਝ ਆਈਟਮਾਂ ਦੀ ਪ੍ਰੋਓਡੀਸਿਟੀ ਵਿੱਚ ਸੋਧ ਕਰਨ ਦੇ ਸੁਝਾਅ ਦਿੱਤੇ ਗਏ, ਇਹ ਸੋਧਾਂ ਫਾਇਨਲ ਤੌਰ ਤੇ ਕਰ ਦਿੱਤੀਆਂ ਹਨ।

ਇੰਜ: ਵਿਜੈ ਕੁਮਾਰ ਚੋਪੜਾ, ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਬਿਜਲੀ) ਪੰਜਾਬ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭ ਤੇ ਮ ਵੱਲੋਂ ਸੁਝਾਅ ਦਿੱਤਾ ਗਿਆ ਕਿ CPWD Maintenance Manual-2012 ਵਿੱਚ ਦਰਸਾਏ ਅਨੁਸਾਰ ਵੱਖ-ਵੱਖ ਇਮਾਰਤਾਂ ਲਈ ਬਜਟ ਨਾਰਮ ਭਾਵ ਕਿ ਪਲਿੰਥ ਏਰੀਆ ਰੇਟਸ ਵੀ ਫਿਕਸ ਕੀਤੇ ਜਾਣੇ ਚਾਹੀਦੇ ਹਨ ਤਾਂ ਜ਼ੋ ਬਜਟ ਅਨੁਮਾਨ ਤਿਆਰ ਕਰਨ ਲਈ ਇਮਾਰਤਾਂ ਉੱਤੇ ਖਰਚੇ ਦੀ ਸੀਮਾ ਨਿਸਚਤ ਕਰਨ ਲਈ ਵੀ ਨਾਰਮ ਨਿਰਧਾਰਤ ਕੀਤੇ ਜਾ ਸਕਣ। CPWD ਵੈਬਸਾਈਟ ਤੇ Latest Maintenance Manual-2012 ਵਿੱਚ ਉਪਲੱਬਧ ਡਾਟਾ ਦੇ ਆਧਾਰ ਤੇ ਰੇਟ ਤਿਆਰ ਕਰਕੇ ਅੱਪਡੇਟ ਕਰਕੇ Annexure-5 ਵਿੱਚ ਦਰਸਾ ਦਿੱਤੇ ਗਏ ਹਨ।

ਮੀਟਿੰਗ ਵਿੱਚ ਇਹ ਵੀ ਵਿਚਾਰ ਕੀਤਾ ਗਿਆ ਕਿ ਫੀਲਡ ਦਫਤਰਾਂ ਵਿੱਚੋਂ ਜੋ ਅਨੁਮਾਨ ਪ੍ਰਾਪਤ ਹੁੰਦੇ ਹਨ, ਉਨ੍ਹਾਂ ਵਿੱਚ ਸਾਰੀਆਂ ਆਈਟਮਾਂ ਲੈਣਾ ਸੰਭਵ ਨਹੀਂ ਹੁੰਦਾ, ਬਹੁਤ ਸਾਰੀਆਂ ਆਈਟਮਾਂ ਮੌਕੇ ਤੇ ਕੰਮ ਤੁਰੂ ਹੋਣ ਤੇ ਨਜ਼ਰ ਵਿੱਚ ਆਉਂਦੀਆਂ ਹਨ। ਇਸ ਕਰਕੇ ਸੀ.ਪੀ.ਡਬਲਯੂ.ਡੀ. ਪੈਟਰਨ ਤੇ ਐਟੂਅਲ ਕਿੰਪਣ ਅਤੇ ਸਪੈਸਲ ਰਿਪੇਅਰ ਦੇ ਨਾਰਮ ਪ੍ਰਤੀ ਵਰਗ ਫੁੱਟ ਵੀ ਨਿਰਧਾਰਤ ਕਰਨੇ ਚਾਹੀਦੇ ਹਨ। ਇਸ ਦੇ ਲਈ ਐਟੂਅਲ ਰਿਪੇਅਰ ਦੇ ਅਨੁਮਾਨ ਵਿੱਚ ਛੋਟੀਆਂ-ਛੋਟੀਆਂ, ਬੋੜੀਆਂ-ਬੋੜੀਆਂ ਵੱਖ-ਵੱਖ ਆਫਟਨਾਂ ਦੀ ਸੁਹਤ ਦੇ ਉਪਰੰਧ ਕਰਨ ਲਈ Plinth Area Rate for unforeseen petty repair ਗਿਆ ਸਮਝ ਕਰਮਾਤ ਕਰ ਦਿੱਤੇ ਹਨ।

ਸਾਰੇ ਅਧਿਕਾਰੀਆਂ ਵੱਲੋਂ ਮੋਨਟੀਨੈੱਸ/ਸਲਾਨਾ ਮੁਰੰਮਤ ਅਤੇ ਸਪੈਸ਼ਲ ਰਿਪੇਅਰ ਦੇ ਨਾਰਮ ਨੱਥੀ ਅਨੈਕਚਰ-2, ਅਨੈਕਚਰ-3, ਅਨੈਕਚਰ-4 ਅਤੇ ਅਨੈਕਚਰ-5 ਅਨੁਸਾਰ ਸਰਬਸੰਮਤੀ ਨਾਲ ਪ੍ਰਵਾਨ ਕੀਤੇ ਗਏ। ਇਹ ਨਾਰਮ ਹਰ ਤਰ੍ਹਾਂ ਦੀਆਂ ਸਰਕਾਰੀ ਇਮਾਰਤਾਂ ਦੇ ਸਿਵਲ ਵਰਕਸ ਮੈਨਟੀਨੈੱਸ ਲਈ ਇਹ ਪੱਤਰ ਜਾਰੀ ਹੋਣ ਦੀ ਮਿਤੀ ਤੋਂ ਲਾਗੂ ਹੋਣਗੇ। ਅੰਤ ਵਿੱਚ ਕਨਵੀਨਰ ਵੱਲੋਂ ਸਾਰੇ ਹਾਜਰ ਹੋਏ ਮੈਂਬਰਾਂ /ਅਧਿਕਾਰੀਆਂ ਦਾ ਧੰਨਵਾਦ ਕੀਤਾ ਗਿਆ।

ਨੱਥੀ/ਉਪਰੋਕਤ ਅਨੁਸਾਰ

–ਮੁੱਖ ਇੰਜੀਨੀਅਰ (ਹੈ.ਕ.)

ਕਮ- ਨੌਡਲ ਅਫਸਰ (ਇਮਾਰਤਾਂ), ਪੰਜਾਬ, ਨੂੰ ਲੋ:ਨਿ:ਵਿ: ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਪਟਿਆਲਾ। ਨਿਸ਼ਸ਼ਿਸ਼ੀ

# Maintenance Norms for Civil Engineering Works in Government Buildings ANNUAL REPAIRS

Annual repairs/maintenance works are carried out by Punjab PWD B&R in all the Government buildings. The works which are to be attended such as the works of periodical nature like White washing, colour washing, distempering, painting and minor repair of various component from buildings etc are called Annual Repair works and these are generally undertaken through system of contracts.

- (i) White Washing, Colour washing, dry distempering, snowcem etc.,
- (ii) Enamel Painting to Wooden or Steel Joinery/Gate Grill etc.
- (ii) Oil Bound Distemper, Plastic Emulsion Paint, sprit polishing etc.
- (iii) Replacement of broken glass / mirror.
- (iv) Replacement of damaged wire gauge.
- (v) Cleaning of glass pans, blinds/curtains etc.
- (vi) Rubbing and polishing of terrazzo floor/marble floor/ kota stone
- (vii) Repairs/replacement of flooring, skirting, dado and plaster.
- (viii) Repairs/Replacement of doors, window frames and shutters. Repairs/Replacement of door and window fittings.

The periodicity of various items of Annual repairs is indicated in Annexure-4. The periodicity is one years for white washing and two colour washing and three years for painting. The items to be executed may be Taken /done 100% on periodical basis or Taken in proportion to its periodicity. In addition, works such as patch repair to plaster, minor repairs to various items of work, replacement of glass panes, replacement of wire gage damaged etc., which are not emergent works and are considered to be of routine type, can be collected and attended to for a group of houses/buildings at a time and particular period of financial year, depending upon the exigency. The yard stick for annual repairs cover the above facilities and Guidelines for various provisions to prepare annual maintenance estimates are described in Annexure

- 4. Guidelines shall be followed for planning and execution of Annual repair works.

The total estimated cost of maintenance of a building / structure during a year shall be within the prescribed limits as approved by the Government from time to time, for Annual repairs. The existing permissible plinth area rates for various types of buildings approved for this purpose are as in Annexure - 5. These may be suitably increased by 5% per annum in the relevant year.

Programme for carrying out annual repairs shall be drawn up at the commencement of each financial year as per rule.

### Maintenance Norms for Civil Engineering Works in Government Buildings SPECIAL REPAIR

As the building ages, there is deterioration to the various parts of the building and services. Major repairs and replacement of elements become inevitable. It becomes necessary to prevent the structure from deterioration and undue wear and tear as well as to restore it back to its original conditions to the extent possible. The following types of works in general are undertaken under special repairs: -

- White Washing, Colour washing, distempering etc., after completely scrapping the existing finish and preparing the surface afresh.
- Painting after removing the existing old paint from various members.
- Provision of water proofing treatment to the roof such as tile terracing, tar-felt (ii) etc. All the existing treatments known are supposed to last satisfactorily only (iii) for a period of about ten years.
- Repairs of internal roads and pavements. (IV)
- Repairs/replacement of flooring, skirting, dado and plaster. (V)
- Repairs/Replacement of doors, window frames and shutters. (VI)
- Repairs/Replacement of door and window fittings. (VII)
- Any other item for repair / replacement. (VIII)

The periodicity of various items of to be executed is indicated in Annexure-4. For execution of any item under Annual repair it covers in plinth area rate provision in A/R estimate. If these items are required to be executed beyond the limit provided in annual repair estimate then it will be executed under special repair with provision in proportion to its periodicity or actual as per site conditions. The yard stick for annual repairs cover the above facilities and Guidelines for various provisions to prepare annual maintenance estimates are described in Annexure - 4. Guidelines shall be followed for planning and execution of special repair works.

The total estimated cost of maintenance of a building / structure during a year shall be within the prescribed limits as approved by the Government from time to time, for Annual repairs. The existing permissible plinth area rates for various types of buildings approved for this purpose are as in Annexure - 5. These will be suitably increased by 10% per annum in the relevant year.

The replacement, renovation and major repairs become inevitable as the periodicity/life of all the components are not identical.

The amount of Special Repairs is permitted to be carried forward up to five years wherever.

### Maintenance Norms for Civil Works in Government Buildings

## PLINTH AREA RATES/ LIMITS FOR MAINTENANCE OF CIVIL WORKS

Base Year 01.01.2018

		Annual	Special Re	pairs	40
SI. No.		Repair	Age 0-20 years (Rs. /Sqm.)	Age 21-40 years (Rs./Sqm.)	(Rs./Sqm.)
		3	4	5	6
1	2	3			
	RESIDENTIAL BUILDINGS				1.50.00
1.	All type of Residences (Other than Sr. No. 2 & 4 below)	106.00	65.00	112.00	156.00
2	M Ps Flats Ministers	212.00	90.00	150.00	210.00
	Bunglows, Ministers, Hon'ble				
	IAS/IPS Officers Residences	137.00	65.00	112.00	156.00
3	Hostels	137.00	00.00		
		Actuals	Actuals	Actuals	Actuals
4	Hon'ble Chief Minister	Actuals			
	NON-RESIDENTIAL BUILDIN	G		1400.00	270.00
	All non- residential /office	120.00	115.00	190.00	210.00
	buildings		225.00	300.00	300.00
2	Secretariat -1 and 2	150.00	90.00	150.00	200.00
3.	District Administrative Complexes, Tehsi Complexes, Sub Tehsi	1	90.00		
	Complexes.	100.00	90.00	150.00	200.00
4.	Judicial Court Complex	120.00	90.00	155.00	215.00
5.		100.00	180.00	300.00	400.00
6		300.00	100.00		
		300.00	180.00	300.00	400.00
7	Dispensaries	300.00	100.50		

NOTES:- (1) The above plinth area rates do not cover expenditure on Conservancy

(2) These rates are only for budget provision / annual programme.

(3) Detailed estimated will be prepared as per norms for AR & SR & quantity of respective building.

# Maintenance Norms for Civil Works in Government Buildings

Priodicity of Variouse Items of Civil Works

For Annual Repair  1 1 1  ashing (Two coats)  For Annual Repair  For Annual Repair  1 1 1  ashing (Two coats)  For Annual Repair  1 1 1  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  1 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  1 2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  1 1 1  2 2 2  ashing (Two coats)  For Annual Repair  I 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  For Annual Repair  I 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  For Annual Repair  I 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  For Annual Repair  I 1 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  For Annual Repair  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  For Annual Repair  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 1 1 1  I 2 2 2  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3 3 3  ashing (Two coats)  I 2 2 3		of Chief	Engineers headed by Chief Engineer(HC PWD B & R Patiala Residential Residentia	ief Engi	neer(HQ	J/NH)-cum- (Þ
For Annual Repair  1 1 2 2 2 2 2 2 2 3 3 3 3 4 Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or 2 2 3 3 3 3 5 Finishing with exterior decorative cement based paint such as 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	No.	Sr. Description of Item No.			Hospital/ Dispensary	
For Annual Repair  White washing (Two coats)  Colour washing (Two coats)  Colour washing (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one survivolation of surface with water resistant gradewall putty match colour complete (Apex or expression)				w	4	
White washing (Two coats)  Colour washing (Two coats)  Distempering with Acrylic washable oil bound distemper (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade. Should over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one washable surface with two coats to be provided with spatular over one surface with watch resistant gradewall putty match colour complete (Apex or equivalent treatment to external putty match colour complete (Apex or equivalent treatment to external putty match colour complete (Apex or equivalent treatment to external putty match colour complete (Apex or equivalent treatment tr	_					
Colour washing (Two coats)  Colour washing (Two coats)  Distempering with Acrylic washable oil bound distemper (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robblacem etc. (One coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one washable surface with match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent			4	_	-	This item may be Taken /done 100% on periodical basis or
Colour washing (Two coats)  Distempening with Acrylic washable oil bound distemper (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  without prepration of surface with water resistant grade.  9 Providing surface treatment to external wall with water resistant grade.  9 Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one washable surface with water coats of surface with water one coats o	_					Taken /
Colour washing (Two coats)  Distempering with Acrylic washable oil bound distemper (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coats of surface with water resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match		The party	1	2	2	4
Distempering with Acrylic Washable Construction Distempering with Spranting of plastic emulsion paint (Interior) (Two coats)  Painting of plastic emulsion paint (Interior) (Two coats)  Painting with synthetic enamel paints in all shades on wood work or 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	N		2	ω	ω	
Painting of plastic emulsion paint (Intenor) (INCOCRE)  Painting with synthetic enamel paints in all shades on wood work or plastered or concrete surface (Two coats)  Painting with synthetic enamel paints in all shades on wood work or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Providing with exterior grade painting outside building already done without preparation of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coats one coats are coats and grade/wall putty match colour complete (Apex or courvalent resistant grade/wall putty match colour complete (Apex or courvalent coats)	w		2	ω	W	
Painting with synthetic enamel paints in all shades on wood work or metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting walls with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Providing with exterior grade painting outside building already done without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Provides surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement pinner including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete.)	A			,	3	
metallic or plastered or concrete surface (Two coats)  Painting with anti corrosive bitumastic paint (Two coats)  Painting with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  without prepration of surface) (Two coat work)  providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent contents)			2	2	7	
Painting with anti corrosive bitumastic paint. (Two coats.)  Finishing walls with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats.)  snowcem, robbiacem etc. (One coats.)  Painting with exterior grade painting outside building already done without prepration of surface.) (Two coat work.)  Providing surface treatment to external wall with water resistant grade.  Providing surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete. (Apex or equivalent resistant grade/wall putty match colour complete.)	(1)		, !	3	2	
Finishing walls with exterior decorative cement based paint such as snowcem, robbiacem etc. (One coats)  snowcem, robbiacem etc. (One coats)  without prepration of surface) (Two coat work)  without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade, anti rusting, antifoaming, high percentage acrylic binder washable surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete)			2	1		
snowcem, robbiacem etc. (One coats) without preparation of surface painting outside building already done without preparation of surface) (Two coat work) without preparation of surface) (Two coat work) without preparation of surface with water resistant grade.  Providing surface treatment to external wall with water resistant grade.  5  10  Washable surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour complete (Apex or equivalent resistant grade/wall putty match colour colour putty match colour putty match colou		whenor decorative cement based paint such		ω	W	
Painting with exterior grade painting outside building already done without prepration of surface) (Two coat work)  without prepration of surface) (Two coat work)  Providing surface treatment to external wall with water resistant grade.  Providing surface treatment to external wall with water resistant grade, anti rusting, antifoaming, high percentage acrylic binder washable surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete ( Apex or equivalent resistant grade/wall putty match colour complete ( Apex or equivalent resistant grade/wall putty match colour complete)				ω	ω	-
Providing surface treatment to external wall with water resistant grade.  Providing surface treatment to external wall with water resistant grade.  Providing surface treatment to external wall with water resistant grade, anti rusting, antifoaming, high percentage acrylic binder antifungal, antifoaming, antifoaming, high percentage acrylic binder washable surface with two coats to be provided with spatula over one washable surface with two coats to be provided with spatula over one coat cement primer including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent primer including preparation of surface with water resistant grade/wall putty match colour complete (Apex or equivalent primer).			C			
		without prepration of survivory (**	1	10	10	
coat cement primer including preparation of surface with water coat cement primer including preparation of surface with water coatstant grade/wall putty match colour complete (Apex or equivalent						
		coat cement primer including preparation to a some coat cement primer including preparation complete (Apex or equipersistant grade/wall putty match colour complete (Apex or equipersistant)	lent			

	,													
22	21	20	19	18	17	ਰੰ	ठ	4	13	12	1	10	>	No.
Plinth Area Rate for unforeseen petty repair/minor replacement of any item.	Cleaning of Chimneys.	Cleaning of Blinds and washing of curtains	Cleaning of glass panes.	Rubbing & polishing of Terrazzo floors/ white marble makrana/kota	Wire guage on steel window / wooden windows	Looking glass	Renewing of glass panes /Forsted glass/Bevelled glass	Spirit polishing	Preparation of surface for paint	Removing old paint with caustic soda solution and preparing surface	Scrapping of emulsion/oil bound paint.	Scrapping of white washing/snowcem/oil bound distemper etc.	2	Description of Item
Rs 15/- per sft	-	-	-	of	15	6	ō	2	Similar to finishing item to be executed	Similar to finishing Item to be executed	Similar to finishing item to be executed	Similar to finishing item to be executed		Residences of Hon'ble Chief Ministers, Ministers, Ministers, Hon'ble MLA's, Hon'ble Judges & Hon'ble Judges & IAS/IPS Officers.
Rs 5/- per sft	1	1	_	ر ن	15	o	o	Ch Ch	ng item to b	ng item to b	ng item to b	ng item to b	w	Office Buildings/ Other Buildings
Rs 5/- per sft	_	_	_	5	15	o	0	5	e executed	e executed	e executed	e executed	4	Residential/ Hospital/ Dispensary
This provision will made for minor repair of civil work items such as repair of joinery, repair of plaster patch work and repair of flooring etc.	- do -	This item may be Taken /done 100% or as per requirement of site.	100% when painting work not done. If painting is done then it is not payable since the cleaning of glass is reponsibility of painter/contractor.	- do -	- do -	- do -	- do -	This item may be Taken /done 100% on periodical basis or Taken /done in proportion to its periodicity.	100% in case of special repair and limited to 20% in annual repair for where scraping/ removal of loose paint /damp area if any. Normal scraping is with in the rate of original	100% in case of special repair and limited to 20% in annual repair for removal of loose surface/damp area if any Normal scraping is with in the rate of original items.	100% in case of special repair and limited to 20% in annual repair for removal of loose surface/damp area if any Normal cleaning/scraping is with in the rate of original items.	100% in case of special repair and limited to 20% in annual repair for removal of loose surface/damp area if any Normal scraping is with in the rate of original items.	On	Remarks

3	12	-7	10	9	00	7	o o	5	4	w	2	_		_	No.
Vitrified floor tiles /Rectified Porcelain tiles /Glazed tiles/Ceramic tiles	Precast chequered tiles	Dry brick on edge flooring.	Red stone, Fine dressed /Rough	Wooden flooring/profile/ skirting	White marble slab/skirting/flooring.	Italian marble flooring after tucking.	Marbo granite flooring	Kota stone flooring	Terrazzo flooring & Skirting	Conglomerate flooring/ topping	Cement plaster in 1:4/1:5/1:6, 10mm/12.5mm/20mm/underside of ceiling 10mm thick.	Cement Pointing 1:3 Very Deep	For Special Repair	2	Description of Item
00	10	20	15	10	25	20	20	20	20	20	15	15			Residences of Hon'ble Chief Minister, Minister, Ministers, Hon'ble MLA's, Hon'ble Judges & IAS/IPS Officers.
œ	10	20	15	10	25	20	20	20	20	20	15	15		3	Office Buildings/ Other Buildings
8	10	20	15	10	25	20	20	20	, 20	20	15	15		4	Hospital/ Dispensary
- do -	- do -	- do -	- do -	- do -	- do -	- do -	-do-	- do -	-do-	-do -	- do -	For execution this item under Annaul repair it covers in plinth area rate provision in A/R estimate. If these items are required to be executed beyond the limit provided in annual repair estimate then it will be executed under special repair with provision in proportion to its periodicity or actual as per site conditions.		On .	Remarks

galle say

in m

29	28	27	26	25	24	23	23	21	20	19	₹	17	क	15	4		No.
Hollock wood wrought planned & fixed in position	Hollock wood moulding/beading	Cup board	Sunmica on cup board	Kail wood planking battens etc	Teak wood cabinet/cupboard along column	Wooden wall/column panelling/partition	Teak wood doors and windows shutters/chowkhats/railing/ cup board chowkhats with teak ply shutter	Wire Gauge Bansam Champ (Assam) wood doors shutter/ windows shutter/chowkhats/wire gauge shutter/cupboard shutters/ cupboards chowkhats	Teakwood panelled & glazed D & W shutter & wire gauge shutters/window /Chawkhats	Hollock wood doors shutter/ windows shutter/chowkhats/wire gauge shutter/cupboard shutters/ cupboards chowkhats	Factory manufactured flush door	Pressed steel frames (Chowkats), Doors and windows frame	Dholpur stone tiles in wall facing (lining)	Factory made cement concrete interlocking floor tiles	Green Orissa/Baroda marble in stairs	2	Description of Item
20	20	5	UT.	10	15	1 8	20	15	20	15	10	15	15	10	15		Residences of Hon'ble Chief Minister, Ministers, Ministers, Hon'ble MLA's, Hon'ble Judges & HAS/IPS Officers.
20	20	10	CO	10	15	00	20	क	20	15	10	15	15	10	15	w	Office Buildings/ Other Buildings
20	20	10	80	10	15	CC	20	15	20	15	10	15	15	10	10	4	Residential/ Hospital/ Dispensary
- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do ·	- do -	- do -	- do -	- do -	-do-	-do-	55	Remarks

45	4	43	42	4	40	39	<u>သ</u>	37	36	35	34	ಜ	(a)	(4)	(4)		7.
									100					31		>	No.
Painting & lettering of No plates	Number/Name plates in Brass with Black Base	Tile facing	Tile terracing.	Barbed wire Fencing.	Wrought iron & mild steel ladders, framed grills grating etc.	Repair of M.S Gate//railing /garage rolling shutters	UPVC water non pressure pipe and connected accessories.	Sun control film fixed on glass.	Brass logo (Punjab Govt. Symbol).	Fibre sheets roofing or walls/on jaffri	Corrugated GI Sheet roofing	Corrugated asbestos Sheet roofing	Helical door Spring./Mortice/internal lock./Hydraulic door closer	Stainless steel handles / tower bolts/ARL /hinges on door & window frames.	Pelmets with of wood such as Hollock /teak/kail wood	2	Description of Rem
ω	3	20	15	10	20	3	20	ch	5	8	15	10	ω	10	25		Hon'ble Chief Minister, Ministers, Hon'ble MLA's, Hon'ble Judges & IAS/IPS Officers.
ω	ω	20	15	10	20	ω	20	10	10	80	15	10	3	10	25	w	Buildings/ Other Buildings
w	ω.	20	15	10	20	W	20	10	10	80	15	10	3	10	25	4	Hospital/ Dispensary
- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do -	- do	5	Kemarks